


TEST REPORT

Lightwater Quarries Ltd
Potgate Quarry
North Stainley
Ripon
HG4 3JN



White
Rose
Laboratory
Services
Ltd

Lumley St • Castleford • WF10 5LB
01977 520625 • enquiries@whiteroselabs.co.uk

Report WRL/16/2975tpfv
Issue date 04/01/18

Material	Type one sub base	Sample N°	S/17/2975
Site	Gebdykes Quarry	Sampled by	ST / LR
Specification	SHW Series 800 C1803	Date sampled	11/12/17
Source	Gebdykes Quarry	Date received	11/12/17
Supplier	Lightwater Quarries Ltd	Date tested	19/12/17
Sample location	Stockpile	Date reported	02/01/18
Sample type	Bulk		
Order number	8815LQ		

BS 812-111 1990 Ten per cent fines value

Material was tested in soaked condition

10% fines value 110 kN

M Randerson
Laboratory Services Director